

CM&EE TMM TASK TEAM SURVEY ON TMM REGULATIONS READINESS June 2023



OPERATIONAL READINESS

Have you applied reasonably practicable measures incl. traffic management controls (e.g. separation, one way traffic flow, etc.) to address risks identified?	Yes	56%
	No	0%
	Partially	44%
Are there areas of significant risk of TMM collision on your mine?	Yes	67%
	No	33%



TECHNOLOGY READINESS

Have you installed CPS (level 9) on your mine?	Yes	15%
	No	85%
If you answered "YES" to Question 7 above, does your system comply to the MOSH Functional and Technical Performance requirements	Yes	36%
	No	64%
Have you formed a CPS implementation team?	Yes	70%
	No	30%
If you answered "YES" to Question 10 above, does the team understand the MOSH CPS technical documentation requirements	Yes	70%
	No	30%
Has the team developed a comprehensive CPS testing strategy and execution plan with dedicated timelines and budget approvals?	Yes	43%
	No	57%



TECHNOLOGY READINESS cont..

Have you identified and selected a potential CxD (Collision warning and avoidance device) supplier?	Yes	59%
	No	41%
Have you conducted a gap assessment with both the TMM and CxD supplier?	Yes	52%
	No	48%
Have you done CPS Testing for all the TMMs that require CPS on your mine in the last 12 months?	Maybe	7%
	Yes	26%
	No	67%
If you answered "YES" to Question 16 above, does your system comply to the MOSH CPS technical documentation requirements?	Yes	50%
	No	50%



DMRE ENGAGEMENT

Have you started engaging with your local DMRE office?	Yes	74%
	No	26%
Have you submitted an application for an extension?	Yes	41%
	No	41%
	N/A	19%
If you answered "YES" to Question 19 above, has your application been accepted or rejected?	Yes	29%
	No	71%
Have you received any Section 54 and/or Section 55 notices with respect to the uplifted TMM regulations, which you consider unreasonable? (If yes, kindly email a copy to smmalatji@mineralscouncil.org.za	Yes	4%
	No	96%

